



**SANITARY SEWER OVERFLOW
ANNUAL REPORT**

DATE: 02/04/16

FACILITY NAME: Olentangy Environmental Control Center

OHIO NPDES PERMIT NO: 4PK00001*JD

PERIOD COVERED BY REPORT: 01/01/2015 - 12/31/2015

CONTACT PERSON

NAME: Mark Chandler

TITLE: Operations Superintendent

MAILING ADDRESS:

7767 Walker Wood Blvd.
Lewis Center OH. 43035

TELEPHONE: 740-549-1906

EMAIL: mchandler@co.delaware.oh.us

I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND AM FAMILIAR WITH THE INFORMATION IN THIS REPORT AND ALL ATTACHMENTS. BASED ON MY INQUIRY OF THOSE PERSONS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION CONTAINED IN THE REPORT, I BELIEVE THAT THE INFORMATION IS TRUE, ACCURATE, AND COMPLETE.



Signature of Official

2-5-16

Date

Operations Superintendent

Title

Enter narrative analysis of WIB patterns by location, frequency and cause.

301 -On 6/20/2015 The maintenance crew by-passed the Leatherlips pump station due to the excessive rain fall. The excessive flow surcharged the pump station beyond it's pumping capacity.

302-On 3/22/15 The Wood cutter pump station is Private and had both pumps out and a by- pass pump was set up. The by-pass pump quit working and back up the main lines. This got multiple homes.