


41833001076000
5542 Columbus
Pike, Ltd.
O.R. 551, Pg. 1179

41833001075000
NGJLT
Company, LLC
O.R. 951, Pg. 589



41833001078000
Timber Lake-
Liberty LLC
O.R. 1279, Pg. 2805
1.68 AC.

41833001078001
Timber Lake-
Liberty LLC
O.R. 1046, Pg. 1987
2.15 AC.

41833001079000
AAT
Properties, Ltd.
D.B. 616, Pg. 347
2.00 AC.

41833001081000
SPEEDWAY
SUPERAMERICA LLC
D.B. 637, Pg. 3204
Parcel I
1.07 AC.

41833001082000
SPEEDWAY
SUPERAMERICA LLC
D.B. 637, Pg. 3204
Parcel II
1.63 AC.

41833001083000
G. Michael
Gilliam
D.B. 430, Pg. 768
4.56 AC.

PROP 70'x55'
SAN ESMT
PROP 24" SAN
7.0'x19.0'
GEN. PAD
16.5'x24'
CONTROL BLDG.
PROP FORCEMAIN

10.0'x10.0'
BIOXIDE
10.5'x15.0'
WET WELL

PROP 20" SAN ESMT
41833001080000
AAT
Properties, Ltd.
O.R. 286, Pg. 353
1.00 AC.

HYATTS ROAD

US ROUTE 23

SHANAHAN ROAD

31822002002000
Judith D. Hook,
Trustee
O.R. 10, Pg. 2626
10.00 AC.

31822001021000
Donald K. and Constance J.
Lynch Family Partnership
D.B. 656, Pg. 767
Lynch Family Partnership
D.B. 656, Pg. 767
28.86 AC.


31822002001000
Hyatts-Columbus
Pike LLC
O.R. 768, Pg. 2051
3.55 AC.



SCALE IN FEET
SCALE: 1" = 40'

DELAWARE COUNTY
HYATTS ROAD
LIFT STATION IMPROVEMENTS
OPTION "C"

PREPARED BY:
Stantec
1500 Lake Shore Drive, Suite 100
Columbus, Ohio 43204
(614) 486-4383
(614) 486-4387



U:\173409312\Report\Exhibits\9312_c_Option C.dwg Layout1 Sep 11, 2017 10:02:34am agreming