

SANITARY SEWER OVERFLOW **ANNUAL REPORT**

DATE: 03/25/13

FACILITY NAME: Bent Tree Wastewater Treatment Facility

OHIO NPDES PERMIT NO: 4GS00018*AG

PERIOD COVERED BY REPORT: 01/01/2012-12/31/2012

CONTACT PERSON

NAME: Mark Chandler

TITLE: Operations Manager

MAILING ADDRESS:

7767 Walker Wood Blvd. Lewis Center, OH 43035

TELEPHONE: 740-549-1906

EMAIL: mchandler@co.delaware.oh.us

I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND AM FAMILIAR WITH THE INFORMATION IN THIS REPORT AND ALL ATTACHMENTS. BASED ON MY INQUIRY OF THOSE PERSONS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION CONTAINED IN THE REPORT, I BELIEVE THAT THE INFORMATION IS TRUE, ACCURATE, AND COMPLETE.

3-25-13

Operations Manager

SSO Annual Report Table 1: SSO Identification

Ohio NPDES Permit No.: 4GS00018*AG

Relatification No.	Location Description NA	Regalving W/ettar ^a	Eliminated ^c
	NA		
		_	
		_	
		<u> </u>	
-	· · · · · · · · · · · · · · · · · · ·		_
		· · · · · · · · · · · · · · · · · · ·	
	-		
		,	
	-		

- A. Assign each SSO location a unique identification by numbering them consecutively, beginning with 301.
- B. Enter name of receiving water. If an SSO enters a storm sewer, enter "SS to (name of receiving water)". If an SSO does not reach a receiving water, enter "None".
- C. If an SSO has been eliminated, enter the date of elimination (MM/DD/YY).

Use additional pages as needed.

SSO Annual Report Table 2: SSO Event Information

Ohio NPDES Permit No.: 4GS00018*AG

Date ^A	विकासिक्सिकार्थिकः	lRta∉aiving/Wattar ^{te}	V⁄oluñt∋ ⁿ
		NA	
	·		
		<u> </u>	
-			
			<u> </u>
<u> </u>	-	<u> </u>	<u> </u>
		<u>.</u>	
		<u> </u>	
	-		
		<u> </u>	

- A. Enter date as "MM/DD/YY". Enter "Various" to summarize overflows of less than 1000 gallons from an SSO location.
- B. Enter the unique identification assigned in Table 1.
- C. Enter name of receiving water. If an SSO enters a storm sewer, enter "SS to (name of receiving water)". If an SSO does not reach a receiving water, enter "None".
- D. Enter estimate of volume in MG (millions of gallons). Enter estimate of total volume if summarizing data.

Use additional pages as needed.

SSO Annual Report Table 3: Water In Basement Occurrences Ohio NPDES Permit No.: 4GS00018*AG

Sewenshed _W	WIB Organicances	Causes ^t
NA NA	THE REAL PROPERTY OF THE PARTY	546950
	_	
	_	
		· · · · · · · · · · · · · · · · · · ·
		
		
		
		
		<u> </u>
-		
	·	
	·	
ifotal@ccurrences	0	
	บ	

- A. A sewershed is a specific geographic area, such as a city block or a subdivision, that drains to a common outlet.
- B. Enter the total number of water in basement occurences reported for the sewershed.
- C. Enter all causes that apply: W = extreme weather; E = equipment failure; P = power failure; D = debris in line; R = roots; G = grease; B = other blockages; L = line deterioration; V = vandalism; O = other, provide details.

Use additional pages as needed.

SSO Annual Report: Water In Basement Narrative Ohio

Ohio NPDES Permit No.: 4GS00018*AG

Enter narrative	The Collection system is routinely monitored by the Collections Department and no SSO or WIB occurrences were identified or reported for 2012.	
analysis of WIB	and no SSO or WIB occurrences were identified or reported for 2012.	
patterns by location,		
frequency and cause.		
ŀ		
	,	
ļ		
ļ		
ſ		