



**SANITARY SEWER OVERFLOW
ANNUAL REPORT**

DATE: 03/25/13

FACILITY NAME: Lower Scioto Water Reclamation Facility

OHIO NPDES PERMIT NO: 4PK0004

PERIOD COVERED BY REPORT: 01/01/2012-12/31/2012

CONTACT PERSON

NAME: Mark Chandler

TITLE: Operations Manager

MAILING ADDRESS:

7767 Walker Wood Blvd.
Lewis Center, OH 43035

TELEPHONE: 740-549-1906

EMAIL: mchandler@co.delaware.oh.us

I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND AM FAMILIAR WITH THE INFORMATION IN THIS REPORT AND ALL ATTACHMENTS. BASED ON MY INQUIRY OF THOSE PERSONS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION CONTAINED IN THE REPORT, I BELIEVE THAT THE INFORMATION IS TRUE, ACCURATE, AND COMPLETE.



Signature of Official

3-25-13

Date

Operations Manager

Title



SSO Annual Report Table 3: Water In Basement Occurrences Ohio NPDES Permit No.: 4PK0004

Sewershed ^A	WIB Occurrences ^B	Causes ^C
NA		
Total Occurrences	0	

A. A sewershed is a specific geographic area, such as a city block or a subdivision, that drains to a common outlet.

B. Enter the total number of water in basement occurrences reported for the sewershed.

C. Enter all causes that apply: W = extreme weather; E = equipment failure; P = power failure; D = debris in line; R = roots; G = grease; B = other blockages; L = line deterioration; V = vandalism; O = other, provide details.

Use additional pages as needed.

Enter narrative analysis of WIB patterns by location, frequency and cause.

Lower Scioto is not yet operational.