



**SANITARY SEWER OVERFLOW  
ANNUAL REPORT**

DATE: 01/17/14

FACILITY NAME: Olentangy Environmental Control Center

OHIO NPDES PERMIT NO: 4PK0001\*JD

PERIOD COVERED BY REPORT: 01/1/13 -12/31/13

**CONTACT PERSON**

**NAME:** Mark Chandler

**TITLE:** Operations Manager

**MAILING ADDRESS:**

7767 Walker Wood Blvd.  
Lewis Center OH. 43035

**TELEPHONE:** 740-549-1906

**EMAIL:** mchandler@co.delaware.oh.us

*I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND AM FAMILIAR WITH THE INFORMATION IN THIS REPORT AND ALL ATTACHMENTS. BASED ON MY INQUIRY OF THOSE PERSONS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION CONTAINED IN THE REPORT, I BELIEVE THAT THE INFORMATION IS TRUE, ACCURATE, AND COMPLETE.*

Mark Chandler  
Signature of Official

2-5-2014  
Date

Operations Manager  
Title









Enter narrative analysis of WIB patterns by location, frequency and cause.

301. On 9/18/13 at 9:35 am. call came in from 365 Shale Ridge CT. That they had sewer running across their back yard. The Delaware County Collections crew discovered a blockage in the main line and the blockage was removed and it was cctv to assure no other blockages was present. The Delaware County Collections crew cleaned up everything around the manhole and flushed everything around the manhole.

302. On 11/15/13 at 4:00pm call came in that a contractor bored though 16 inch force main . The Delaware County Collections Crew assure accurate locations of the force main, clean water was used to flush the parking lots and storm drainage areas, return to the area to assure that no residual of spill is evident.

WIB 8/25/13 at 11:00pm. Call came in that 297 Safreed Way had sewer in there basement, the Delaware County Collections crew found the main line had a blockage. They freed the blockage and cctv the main line to assure no other blockages were present. They found a contractor plug and some gravel and removed them from the main line.