



**SANITARY SEWER OVERFLOW
ANNUAL REPORT**

DATE: 01/17/14

FACILITY NAME: Scioto Reserve Wastewater Reuse Facility

OHIO NPDES PERMIT NO: 4MP00009*BM

PERIOD COVERED BY REPORT: 1/1/13-12/31/13

CONTACT PERSON

NAME: Mark Chandler

TITLE: Operations Manager

MAILING ADDRESS:

7767 Walker wood Blvd.
Lewis Center OH. 43035

TELEPHONE: 740-549-1906

EMAIL: mchandler@co.delaware.oh.us

I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND AM FAMILIAR WITH THE INFORMATION IN THIS REPORT AND ALL ATTACHMENTS. BASED ON MY INQUIRY OF THOSE PERSONS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION CONTAINED IN THE REPORT, I BELIEVE THAT THE INFORMATION IS TRUE, ACCURATE, AND COMPLETE.

Mark Chandler
Signature of Official

2-5-2014
Date

Operations Manager
Title



Enter narrative analysis of WIB patterns by location, frequency and cause.

301 On 07/28/13 at 2:05 PM the pump station at the Scioto Reserve Wastewater Reuse Facility had an equipment failure which caused the SSO behind the maintenance garage .The Delaware County Collections / Maintenance crew was on site at 2:45 PM . The pump station was back in service at 3:00 PM The Collections Crew vacuumed up the wastewater beside and behind the Maintenance garage and flushed the area with clean water.