

**SANITARY SEWER OVERFLOW  
ANNUAL REPORT**

**DATE:** 01/19/17

**FACILITY NAME:** Hoover Woods WWTP

**OHIO NPDES PERMIT NO:** 4PA00006\*HD

**PERIOD COVERED BY REPORT:** 01/01/16-12/31/16

**CONTACT PERSON**

**NAME:** Mark Chandler

**TITLE:** Operations Superintendent

**MAILING ADDRESS:**

7767 Walker Wood Blvd.  
Lewis Center, Ohio 43035

**TELEPHONE:** 740-833-2226

**EMAIL:** mchandler@co.delaware.oh.us

*I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND AM FAMILIAR WITH THE INFORMATION IN THIS REPORT AND ALL ATTACHMENTS. BASED ON MY INQUIRY OF THOSE PERSONS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION CONTAINED IN THE REPORT, I BELIEVE THAT THE INFORMATION IS TRUE, ACCURATE, AND COMPLETE.*



Signature of Official

1-19-17

Date

Operations Superintendent

Title





SSO Annual Report Table 3: Water In Basement Occurrences Ohio NPDES Permit No.: 4PA00006\*HD

Sewershed <sup>A</sup>	WIB Occurrences <sup>B</sup>	Causes <sup>C</sup>
N/A	0	
Total Occurrences	0	

A. A sewershed is a specific geographic area, such as a city block or a subdivision, that drains to a common outlet.

B. Enter the total number of water in basement occurrences reported for the sewershed.

C. Enter all causes that apply: W = extreme weather; E = equipment failure; P = power failure; D = debris in line; R = roots; G = grease; B = other blockages; L = line deterioration; V = vandalism; O = other, provide details.

Use additional pages as needed.

Enter narrative analysis of WIB patterns by location, frequency and cause.

A large, empty rectangular box with a thin black border, intended for the user to enter a narrative analysis of Water In Basement (WIB) patterns. The box is currently blank.