



**SANITARY SEWER OVERFLOW
ANNUAL REPORT**

DATE: 03/08/18

FACILITY NAME: Hoover Woods WWTP

OHIO NPDES PERMIT NO: 4PA00006*HD

PERIOD COVERED BY REPORT: 1/1/17 -12/31/17

CONTACT PERSON

NAME: Mark Chandler

TITLE: Operations Superintendent

MAILING ADDRESS:

7767 Walker Wood Blvd.
Lewis Center, Ohio 43035

TELEPHONE: 740-833-2226

EMAIL: mchandler@co.delaware.oh.us

I CERTIFY UNDER PENALTY OF LAW THAT I HAVE PERSONALLY EXAMINED AND AM FAMILIAR WITH THE INFORMATION IN THIS REPORT AND ALL ATTACHMENTS. BASED ON MY INQUIRY OF THOSE PERSONS IMMEDIATELY RESPONSIBLE FOR OBTAINING THE INFORMATION CONTAINED IN THE REPORT, I BELIEVE THAT THE INFORMATION IS TRUE, ACCURATE, AND COMPLETE.

Signature of Official

3-13-18

Date

Title

Identification No. ^A	Location Description	Receiving Water ^B	Eliminated ^C
	NONE.	N/A	

A. Assign each SSO location a unique identification by numbering them consecutively, beginning with 301.

B. Enter name of receiving water. If an SSO enters a storm sewer, enter "SS to (name of receiving water)". If an SSO does not reach a receiving water, enter "None".

C. If an SSO has been eliminated, enter the date of elimination (MM/DD/YY).

Use additional pages as needed.

Enter narrative analysis of WIB patterns by location, frequency and cause.

A large, empty rectangular box with a thin black border, intended for the user to enter a narrative analysis of Water In Basement (WIB) patterns. The box is currently blank.